

Day in the Life of a BGP Update in Cisco IOS

Philip Smith Routing WG, RIPE 45, Barcelona May 2003

Routing WG RIPE45

© 2001, Cisco Systems, Inc. All rights reserved.

Agenda

Cisco.com

Presentation tracks a BGP update through a router running Cisco IOS

Basic BGP Processing Queues...

Cisco.com

UPDATE Arrives from the peer

Goes to input hold queue

Then to tcp queue for right socket on the Route Processor (RP)

- BGP I/O process on RP reads from TCP sockets and puts messages on BGP InQ
- The BGP InQ adds the packet to the input queue for the appropriate peer

Basic BGP Processing BGP Process...

Cisco.com

- Unpacks the prefixes from the UPDATEs
- Begins best path computation:

Path is run through configured incoming filters:

- 1. miscellaneous checks (AS loop etc)
- 2. filter-list

Mutually exclusive

- 3. route-map
- 4. prefix-list OR distribute-list

Path is either discarded, or has attributes modified, or remains unchanged

Basic BGP Processing Path Not Discarded (1)...

Cisco.com

- Compared with other paths for the same prefix
- Best path chosen according to the IOS best path decision algorithm at

www.cisco.com/warp/public/459/25.shtml

 Bestpath for a prefix marked as such in BGP database and sent to RIB for insertion

NB: Existing path in RIB with lower admin distance means that best path will NOT be inserted

Basic BGP Processing Path Not Discarded (2)...

Cisco.com

Insertion into RIB triggers insertion into FIB

New entry in FIB is propagated to the LineCards FIB etc

 Once the path is sent to the RIB, it is flagged that it needs to be sent to peers/peer-group in a BGP update

Basic BGP Processing Update Our Peers...

1.....Cisco.com

• When ready to update our peers with our routes:

Walk BGP table once per peer (or peer-group) looking for bestpaths

Bestpaths sent through outbound filters:

- 1. prefix-list_OR distribute-list
- 2. ORF

Mutually exclusive

- 3. Miscellaneous (AS loop, no-export, etc)
- 4. filter-list
- 5. route-map OR unsuppress-map
- 6. advertise-map (conditional advertisement)

Path is either discarded, or has attributes modified, or remains unchanged

Basic BGP Processing Forming & Sending Updates...

Cisco.com

- Create a new update for each bestpath with a unique attribute combination
- Once reached the end of the walk (or limited by available memory), the updates are enqueued on the peer's output queue
- For peer-groups, the update is reused for each member of the peer-group
- Sending Updates

Updates are packed into TCP messages

Sent to appropriate BGP peers

BGP packets have IP precedence 6

Recent Changes

• Up to 12.0(18)S:

Update algorithm (Normal mode) queued updates every 500 updates computed – could lead to slow convergence

• 12.0(18)S1 onwards:

Added new algorithm to aid faster convergence (Init mode – ignores 500 update limit)

Aggressive on memory – selected depending on available router memory

• 12.0(21)S1 onwards:

Limits added to BGP's memory usage to ensure that CEF and BGP live together more peacefully

• 12.0(22)S onwards:

Init mode and normal mode replaced with a new algorithm which offers fast convergence but better safeguards against excessive memory usage

Details BGP Scanner

Cisco.com

BGP Scanner

This runs every 60 seconds

Timer can be changed if desired:

bgp scan-time <5-60> - units in seconds

Multiprotocol BGP

Adds Import Scanner – runs every 15 seconds

Only applies to VPNv4 AF

Timer can be changed if desired:

bgp scan-time import <5-60> - units in seconds

Details BGP Scanner – What does it do??

Cisco.com

• Housekeeping!

Evaluates redistribution and network statements

Conditional advertising

Route flap damping clean up (delete old & history entries)

And most importantly of all:


• Checks validity of all entries in BGP table

Invalid next hop results in attempt to recompute alternative path, update to peers, etc

Very Simple Walk Through...

Cisco.com

- R1 originates 2.0.0.0/8 into BGP
- Track the propagation of the prefix from R1 through R2 to R3



Walk Through R1 adds configuration for 2.0.0.0/8

Cisco.com

Operator configures prefix R1(config-router)#net 2.0.0.0 10:34:48.350 BGP: Import timer expired. Walking from 1 to 1 10:35:03.350 BGP: Import timer expired. Walking from 1 to 1 10:35:18.350 BGP: Import timer expired. Walking from 1 to 1 **BGP scanner runs** 10:35:33.350 BGP: Performing BGP general scanning 10:35:33.350 BGP(0): scanning IPv4 Unicast routing tables 10:35:33.358 BGP(IPv4 Unicast): Performing BGP Nexthop scanning for general scan 10:35:33.358 BGP(1): scanning IPv6 Unicast routing tables 10:35:33.358 BGP(IPv6 Unicast): Performing BGP Nexthop scanning for general scan 10:35:33.362 BGP(2): scanning VPNv4 Unicast routing tables 10:35:33.362 BGP(VPNv4 Unicast): Performing BGP Nexthop scanning for general scan 10:35:33.362 BGP(3): scanning IPv4 Multicast routing tables 10:35:33.370 BGP(IPv4 Multicast): Performing BGP Nexthop scanning for general scan

Walk Through **R1 Scanner does its housekeeping**

Cisco.com

New net entry spotted

10:35:33.378 BGP(0): route 2.0.0.0/8 up

10:35:33.378 BGP(0): nettable walker 2.0.0.0/8 route sourced locally

10:35:33.378 BGP(0): 192.168.4.129 computing updates, afi 0, neighbor version 64, table version 65, starting at 0.0.0.0

10:35:33.378 BGP(0): 192.168.4.129 send UPDATE (format) 12.0.0.0/8, next 192.168.4.133, metric 0, path

10:35:33.378 BGP(0): 192.168.4.129 1 updates engueued (average=60, maximum=60)

10:35:33.378 BGP(0): 192.168.4.129 update run completed, afi 0, ran for 0ms, neighbor version 64, start version 65, throttled to 65 note

time! 10:35:48.378 BGP: Import timer expired. Walking from 1 to 1 10:36:03.379 BGP: Import timer expired. Walking from 1 to 1 10:36:18.379 BGP: Import timer expired. Walking from 1 to 1 10:36:33.379 BGP: Performing BGP general scanning 10:36:33.379 BGP(0): scanning IPv4 Unicast routing tables 10:36:33.387 BGP(IPv4 Unicast): Performing BGP Nexthop scanning for general scan

Update created and sent

Walk Through What happens on R2?

Cisco.com

10:35:26.327 BGP: Import timer expired. Walking from 1 to 1 10:35:33.391 BGP(0): 192.168.4.133 rcvd UPDATE w/ attr: nexthop 192.168.4.133. origin i. metric 0. path 100 Compare 10:35:33.391 BGP(0): 192.168.4.133 rcvd 2.0.0.0/8 with ^{10:35:33.378} 10:35:33.391 BGP(0): Revise route installing 1 of 1 route for 2.0.0.0/8 -> 192.168.4.133(main) to main IP table 10:35:33.391 RT: add 2.0.0.0/8 via 192.168.4.133, bgp metric [20/0] 10:35:34.491 BGP(0): 192.168.9.13 computing updates, afi 0, neighbor version 33, table version 34, starting at 0.0.0.0 10:35:34.491 BGP(0): 192.168.9.13 starting fmt at 33/0 0.0.0.0, cache 0 0, abort = 1 10:35:34.491 BGP(0): 192.168.9.13 send UPDATE (format) 2.0.0.0/8, next 192.168.9.14, metric 0, path 100 10:35:34.491 BGP(0): 1 updates (average = 55, maximum = 55)10:35:34.491 BGP(0): Set update-group 1 eng version to 34 192.168.9.13 10:35:34.491 BGP(0): 192.168.9.13 fmt 1, eng Done vers set to 34/0 34/0 0.0.0.0 note 10:35:34.491 BGP(0): 192.168.9.13 update run completed, afi 0, ran for 0ms, neighbor version 34, start version 34, throttled to 34 time! **10:35:34.491** BGP(0) : Initial update finished for 192.168.9.13 10:35:34.491 BGP(0): 1 done. vers 34 34, tbl 34 init 34

Walk Through More from R2

We get

Cisco.com

10:35:34.491 BGP(0): 192.168.4.133 computing updates, afi 0, neighbor version 33, table version 34. starting at 0.0.0.0 10:35:34.491 BGP(0): 192.168.4.133 starting fmt at 33/0 0.0.0.0, cache 0 0, abort = 1 10:35:34.491 BGP(0): Set update-group 2 eng version to 34 10:35:34.491 BGP(0): 192.168.4.133 fmt 0, eng Done vers set to 34/0 34/0 0.0.0.0 10:35:34.491 BGP(0): 192.168.4.133 update run completed, afi 0, ran for 0ms, neighbor version 34, start version 34, throttled to 34 10:35:34.491 BGP(0) : Initial update finished for 192.168.4.133 10:35:34.491 BGP(0): 2 done. vers 34 34. tbl 34 init 34 10:35:34.491 BGP(0): Reset update-group 1 versions from 34 34 to 0 0 10:35:34.491 BGP(0): Reset update-group 2 versions from 34 34 to 0 0 update from 10:35:34.503 BGP(0): 192.168.9.13 rcv UPDATE w/ attr: nexthop 192.168.9.13, R3 too – 12ms origin i, originator 0.0.0.0, path 300 200 100, community , extended community update from to process! 10:35:34.503 BGP(0): 192.168.9.13 rcv UPDATE about 2.0.0.0/8 -- DENIED due to: AS-PATH contains our own AS:

10:35:41.327 BGP: Import timer expired. Walking from 1 to 1

Walk Through What happens on R3?

Cisco.com

10:35:27.910 BGP: Import timer expired. Walking from 1 to 1

10:35:34.494 BGP(0): 192.168.9.14 rcvd UPDATE w/ attr: nexthop 192.168.9.14, origin i, path 200 100

Compare with 10:35:34.498 BGP(0): 192.168.9.14 rcvd 2.0.0.0/8 10:35:33.378

from R1 and 10:35:34.498 BGP(0): Revise route installing 1 of 1 route for 2.0.0.0/8 ->

10:35:34.491 192.168.9.14 to màiń IP table

from R2 10:35:34.498 RT: add 2.0.0.0/8 via 192.168.9.14, bgp metric [20/0]

10:35:34.498 BGP(0): 192.168.9.14 computing updates, afi 0, neighbor version 132, table version 134, starting at 0.0.0.0

10:35:34.498 BGP(0): 192.168.9.14 send UPDATE (format) 2.0.0.0/8, next 192.168.9.13, metric 0, path 200 100

10:35:34.502 BGP(0): 192.168.9.14 1 updates enqueued (average=57, maximum=57)

10:35:34.502 BGP(0): 192.168.9.14 update run completed, afi 0, ran for 4ms, neighbor version 132, start version 134, throttled to 134

10:35:42.910 BGP: Import timer expired. Walking from 1 to 1

10:35:57.910 BGP: Import timer expired. Walking from 1 to 1

Walk Through Operator removes 2.0.0.0/8 from R1

Cisco.com

Operator removes prefix

BGP scanner runs

R1(config-router)#no net 2.0.0.0

10:38:18.435 BGP: Import timer expired. Walking from 1 to 1

10:38:33.435 BGP: Performing BGP general scanning —

10:38:33.435 BGP(0): scanning IPv4 Unicast routing tables

10:38:33.443 BGP(IPv4 Unicast): Performing BGP Nexthop scanning for general scan

10:38:33.443 BGP(0): nettable_scan: invalidate local path for 2.0.0.0/8 2/8 gone!

10:38:33.443 BGP(0): nettable_scan: invalidate sourced path for 2.0.0.0/8

10:38:33.443 BGP(0): no valid path for 2.0.0.0/8

10:38:33.447 BGP(1): scanning IPv6 Unicast routing tables

10:38:33.447 BGP(IPv6 Unicast): Performing BGP Nexthop scanning for general scan

10:38:33.447 BGP(2): scanning VPNv4 Unicast routing tables


10:38:33.447 BGP(VPNv4 Unicast): Performing BGP Nexthop scanning for general scan

10:38:33.447 BGP(3): scanning IPv4 Multicast routing tables

10:38:33.455 BGP(IPv4 Multicast): Performing BGP Nexthop scanning for general scan

Walk Through R1 Scanner does its housekeeping

Cisco.com



Walk Through What happens on R2?

	Cisco.com				
	10:38:26.376 BGP: Import timer expired. Walking from 1 to 1				
Compare with 10:38:33.463	10:38:33.476 BGP(0): 192.168.4.133 rcv UPDATE about 2.0.0.0/8 – withdrawn				
	10:38:33.476 BGP(0): no valid path for 2.0.0.0/8				
	10:38:33.476 BGP(0): nettable_walker 2.0.0.0/8 no best path				
	10:38:33.476 RT: del 2.0.0.0 via 192.168.4.133, bgp metric [20/0]				
	10:38:33.476 RT: delete network route to 2.0.0.0				
	10:38:34.576 BGP(0): 192.168.9.13 computing updates, afi 0, neighbor version 34, table version 35, starting at 0.0.0.0				
	10:38:34.576 BGP(0): 192.168.9.13 starting fmt at 34/0 0.0.0.0, cache 0 0, abort = 1				
	10:38:34.576 BGP(0): 192.168.9.13 send unreachable 2.0.0.0/8				
	10:38:34.576 BGP(0): 192.168.9.13 send UPDATE 2.0.0.0/8 – unreachable				
	10:38:34.576 BGP(0): 1 updates (average = 25, maximum = 25)				
note time!	10:38:34.576 BGP(0): Set update-group 1 enq_version to 35 192.168.9.13				
	10:38:34.576 BGP(0): 192.168.9.13 fmt 1, enq Done vers set to 35/0 35/0 0.0.0.0				
	10:38:34.576 BGP(0): 192.168.9.13 update run completed, afi 0, ran for 0ms, neighbor version 35, start version 35, throttled to 35				
	10:38:34.576 BGP(0) : Initial update finished for 192.168.9.13				
	10:38:34.576 BGP(0): 1 done. vers 35 35, tbl 35 init 35				

Walk Through More from R2

1

10:38:34.576 BGP(0): 192.168.4.133 computing updates, afi 0, neighbor version 34, table version 35, starting at 0.0.0. 10:38:34.576 BGP(0): 192.168.4.133 starting fmt at 34/0 0.0.0, cache 0 0, abort = 1 10:38:34.576 BGP(0): Set update-group 2 enq_version to 35 10:38:34.576 BGP(0): 192.168.4.133 fmt 0, enq Done vers set to 35/0 35/0 0.0.0 10:38:34.576 BGP(0): 192.168.4.133 update run completed, afi 0, ran for 0ms, neighbor version 35, start version 35, throttled to 35 10:38:34.576 BGP(0): 1 Initial update finished for 192.168.4.133 10:38:34.576 BGP(0): 2 done. vers 35 35, tbl 35 init 35 10:38:34.576 BGP(0): Reset update-group 1 versions from 35 35 to 0 0 10:38:34.576 BGP(0): Reset update-group 2 versions from 35 35 to 0 0 10:38:34.576 BGP(0): 192.168.9.13 rcv UPDATE about 2.0.0.0/8 – withdrawn 10:38:41.376 BGP: Import timer expired. Walking from 1 to 1

Walk Through What happens on R3?

Cisco.com

10:38:27.959 BGP: Import timer expired. Walking from 1 to 1

10:38:34.579 BGP(0): 192.168.9.14 rcv UPDATE about 2.0.0.0/8 – withdrawn

10:38:34.579 BGP(0): no valid path for 2.0.0.0/8 Compare with

10:38:33.476 10:38:34.579 BGP(0): nettable_walker 2.0.0.0/8 no best path

from R1 and 10:38:34.576 10:38:34.579 RT: del 2.0.0.0 via 192.168.9.14, bgp metric [20/0]

from R2 10:38:34.579 RT: delete network route to 2.0.0.0

10:38:34.583 BGP(0): 192.168.9.14 computing updates, afi 0, neighbor version 134, table version 136, starting at 0.0.0.0

10:38:34.583 BGP(0): 192.168.9.14 send unreachable 2.0.0.0/8

10:38:34.583 BGP(0): 192.168.9.14 send UPDATE 2.0.0.0/8 – unreachable

10:38:34.583 BGP(0): 192.168.9.14 1 updates enqueued (average=25, maximum=25)

10:38:34.583 BGP(0): 192.168.9.14 update run completed, afi 0, ran for 0ms, neighbor version 134, start version 136, throttled to 136

10:38:42.959 BGP: Import timer expired. Walking from 1 to 1

10:38:57.959 BGP: Import timer expired. Walking from 1 to 1

10:39:12.959 BGP: Performing BGP general scanning

Walk Through Summary

Cisco.com

• Update coming into IOS router is processed immediately, and sent onwards if appropriate:

Time required depends on number of prefixes, speed of processor, etc

General case dependent on "advertisement interval"

Locally configured routes await the BGP scanner...

...when BGP network statement exists, and route is introduced by static, connected, IGP, etc

Walk Through Flap Damping on R2 and R3

Cisco.com

- After 3 withdraw and announce of 2.0.0.0/8
- R1

16:38:42.236 BGP(0): route 2.0.0.0/8 up

16:38:42.236 BGP(0): nettable_walker 2.0.0.0/8 route sourced locally

16:38:43.236 BGP(0): 192.168.4.129 computing updates, afi 0, neighbor version 87, table version 88, starting at 0.0.0.0

16:38:43.236 BGP(0): 192.168.4.129 send UPDATE (format) 2.0.0.0/8, next 192.168.4.133, metric 0, path

16:38:43.236 BGP(0): 192.168.4.129 1 updates enqueued (average=60, maximum=60)

16:38:43.236 BGP(0): 192.168.4.129 update run completed, afi 0, ran for 0ms, neighbor version 87, start version 88, throttled to 88

• R2

16:38:43.243 BGP(0): 192.168.4.133 rcvd UPDATE w/ attr: nexthop 192.168.4.133, origin i, metric 0, path 100

16:38:43.247 BGP(0): 192.168.4.133 rcvd 2.0.0.0/8



16:38:43.247 BGP(0): no valid path for 2.0.0.0/8

Walk Through Flap Damping on R2 and R3

Cisco.com

 R2 sees three flaps from R1, so prefix is suppressed when the update arrives on the router

BGP scanner only updates the flap damping counters

BGP Process handles whether the prefix is suppressed or not as the update arrives

• R3 sees no update – R2 suppresses the announcement:

R2#sh ip bgp dam	p flap					
Network	From	Flaps	Duration	Reuse	Path	
*d 2.0.0.0	192.168.4.133	3	00:05:29	00:04:39	100	
R3#sh ip bgp damp flap						
Network	From	Flaps	Duration	Reuse	Path	
h 2.0.0.0	192.168.9.14	3	00:05:36		200 100	

- - - -

Flap Damping Summary

Cisco.com

• If prefix is flapping

Updates are suppressed once suppress limit reached – done by the BGP Process

If prefix is not flapping

Updates sent onwards immediately after they are heard from the neighbour and processed

General case dependent on "advertisement interval"

Other timers: Update Delay

Cisco.com

- IOS has a timer to handle graceful startup of BGP peerings:
- Update-delay:

bgp update-delay <1-3600> – default is 120 seconds

Determines how long BGP process waits before computing bestpaths, updating the routing table, and sending updates

Other timers: Advertisement Interval

Cisco.com

Advertisement interval:

neighbor x.x.x.x min-advertise <1-3600>

eBGP defaults to 30 seconds

iBGP and eiBGP defaults to 5 seconds

This value is the amount of time the router will wait before it generates more updates relating to a prefix change

Other timers: Advertisement Interval (cont)

Cisco.com

• Example of a BGP Update

Walk BGP table & Detect Changes

Generate Update & send the packets

Start minimum adv interval timer when finished

Walk the table again

If any changes detected, DO NOTHING!

We wait until minimum adv interval timer is finished before sending any more updates

Summary

Cisco.com

 Prefix update propagation delay in IOS is purely due to the speed of the processor and the number of updates to be handled – plus:

Min-advertise interval prevents "churn"

Update-delay waits until BGP process is running before generating updates

 Examples for this presentation were tested on 12.2(11)T, 12.0(24)S and 12.2(14)S